Division of Oil, Gas, & Mining Mining Report

09/17/92

MINE ID: M037044 MINE NAME: CUB MINE

> OPERATOR: KELMINE CORPORATION CONTACT: MELVIN R SWANSON ADDRESS: BOX 1383

MOAB UT 84532

PHONE: (801)259-6711

Surface Owner: BLM BLM #: Mineral Owner: BLM Lease #:

Qtr-Qtr-Qtr1 Qtr-Qtr1 Qtr-Qtr-Qtr2 Qtr-Qtr2 Sec Range Town 26 25.0E 30.0S SE SE

Permit Status: APP Mine Type [(S)urface, (U)nderground]: U

Mine Status (PRO, ACT, SUS, RET): SUS

Acreage:

Minerals Mined

DATE RECEIVED	TENTATIVE APPROVAL DATE	FINAL APPROVAL DATE	LAST INSPECTED	
04/19/79	07/26/79	09/07/79	08/31/92	

BOND AMOUNT: 11,008 BOND TYPE: SURETY BOND

ANNUAL REPORT YEAR: 91

NONCOMPLIANCE NOTICES:	0	DATE ISSUED:	/	1	DATE RESOLVED:	1	1
VIOLATIONS:	0	DATE ISSUED:	/	1	DATE RESOLVED:	1	/
REVISIONS:	0	DATE REC'D:	/	1	DATE APPROVED:	1	1
AMENDMENTS:	0	DATE REC'D:	/	1	DATE APPROVED:	1	1

COMMENTS:

THE MINE WAS LAST WORKED IN 1986 AND IS CURRENTLY INACTIVE. CURRENT SURFACE DISTURBANCE IS LESS THAN FIVE ACRES. SURETY NEEDS TO BE REEVALUATED. OPERATOR IS RECLAIMING SITE. WILLIAM JOHNSTON, LOCAL CONTRACTOR IN MOAB DOING WORK AND LEFT UNSIGHTLY & UNSAFE MESS. JIM BOULDEN (ANOTHER CONTRACTOR) WAS NOTIFIED & WILL CLEAN UP THE MESS. SMALL METAL TANKS WILL BE PLACED IN MINE PORTAL, THE PORTAL THEN SEALED AND COVERED. LARGER TANKS MAY BE USED FOR WATER STORAGE BY LOCAL RANCHER.